

Pręty kwadratowe według DIN 1014

wymiar	S355J2G3 / S355JO 18G2A	C45 gat. 45	C60 gat. 60	16/20MnCrS5 16/20HG	42CrMo4S4V 40HM ulepsz.
kwadrat 10	●				
kwadrat 12	●	●			
kwadrat 14	●				
kwadrat 15	●	●			
kwadrat 16	●	●	●		●
kwadrat 18	●	●			
kwadrat 20	●	●		●	●
kwadrat 22	●	●			
kwadrat 25	●	●		●	●
kwadrat 28		●			
kwadrat 30	●	●	●	●	●
kwadrat 32	●	●		●	●
kwadrat 35	●	●	●	●	●
kwadrat 38	●	●			
kwadrat 40	●	●	●	●	●
kwadrat 45	●	●	●	●	●
kwadrat 50	●	●	●	●	●
kwadrat 55	●	●	●	●	●
kwadrat 60	●	●	●	●	●
kwadrat 65	●	●	●	●	●
kwadrat 70	●	●	●	●	●
kwadrat 75	●	●		●	●
kwadrat 80	●	●	●	●	●
kwadrat 85	●	●		●	●
kwadrat 90	●	●	●	●	●
kwadrat 95		●			
kwadrat 100	●	●	●	●	●
kwadrat 110	●	●	●	●	●
kwadrat 120	●	●	●	●	●
kwadrat 130	●	●	●	●	●
kwadrat 140	●	●	●	●	●
kwadrat 150	●	●		●	●
kwadrat 160	●	●		●	●
kwadrat 170	●	●			
kwadrat 180	●	●		●	●
kwadrat 190	●	●			
kwadrat 200	●	●		●	●
kwadrat 210	●	●			
kwadrat 220	●	●			
kwadrat 230	●	●			
kwadrat 240	●	●			●
kwadrat 250	●	●			
kwadrat 260		●		●	●
kwadrat 280		●		●	
kwadrat 290		●			
kwadrat 300					●